

TECH UPDATE

Issue 24 2017

Solution 3000 Firmware update released V1.3.0.1



1. Firmware update note

- Bosch have released a firmware update to the Solution 3000 Intrusion
For additional information is located at this URL.

<http://csp-info.com/wp/index.php/2017/07/14/new-solution-3000-firmware-update-released-v1-3-0-1/>

2. Added Features

- A Link Plus defaults for B426 added to factory default settings.
- Global EOL support added for normally open sensor.'
- When 2nd IP/GPRS module is used, Route 3 and 4 reports use it.
- Master user can now change user code area allocations
- By default, panel will not answer A Link call without call-back number
- Added support for a total of 4 monitoring station destinations

3. Resolved Issues

- Entry Exit beeps heard only on one keypad when multiple installed
- Comms Fault condition when domestic dial call not answered
- LED indicates on TEXT keypad do not extinguish after 60sec idle
- TEXT keypad beeps on backlight time out
- Chime zone type doesn't trigger day alarm

Did you know that ALL our news, product information and tech updates are on our Facebook & Twitter pages?

